

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

OGM Dennis Ware Controller

Inspection Report

Permit Number:	C0070038		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, October 14, 2008		
Start Date/Time:	10/14/2008 10:00:00 AM		
End Date/Time:	10/14/2008 12:00:00 PM		
Last Inspection:	Tuesday, September 30, 2008		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 1800

Accepted by: jhelfric

11/10/2008

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Total Disturbed

Phase I

Phase II

Phase III

Permit Type: PERMANENT COAL PROGRAM

Site: WILLOW CREEK MINE

Permit Status: ACTIVE

14,662.49 Total Permitted

Current Acreages

Mineral Ownership

Types of Operations

✓ Federal

State County Fee

Other

✓ Loadout

Processing Reprocessing

✓ Underground

☐ Surface

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division that the second guarter of 2008 surface and UPDES water monitoring information for the Willow Creek Mine was in the electronic data base pipeline ready for uploading.

The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit, which was renewed April 24, 2006.

There are no pending compliance actions.

There is currently no activity at this site.

Inspector's Signature:

Steve/Demczak/Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Date

Wednesday, October 15, 2008

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 14, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		~	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		V	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	✓			
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 14, 2008

Page 3 of 3

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and would function during a storm event. There were no signs of erosion.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond at the CEU building was inspected and no hazardous conditions were noticed. This pond is still inspected by the permiteee but has received phase III bond release and given to CEU.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclaim site has been completely pock. There were no signs of erosion.

4.d Hydrologic Balance: Water Monitoring

Secons quarter of 2008 water data was sent to the Division.

4.e Hydrologic Balance: Effluent Limitations

No discharge from the sediment pond located by CEU for the second quarter of 2008.

8. Noncoal Waste

Area was clear of non-coal waste.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The mine site is backfilled and graded.